

Fig. 1






Fig. 2



SHIMADA et al.Q68419
STRUCTURE INSPECTION APPARATUS
Filed: March 6, 2002
Robert J. Seas, Jr.202-293-7060
3 of 15

Fig. 3





Fig. 4

(a)



(b)





Fig. 5

(c)



(d)




Fig. 6




Fig. 7




Fig.8




Fig. 9




Fig. 10




Fig. 11




Fig. 12




Fig. 13




Fig. 14




Fig. 15





Fig. 16



SHIMADA et al. Q68419
STRUCTURE INSPECTION APPARATUS
Filed: March 6, 2002
Robert J. Seas, Jr. 202-293-7060
15 of 15

Fig. 17

